LORP Measuring Station	Augment Daily Avg	ing Flows 15 Day Avg	Owen Daily Avg		Flows # Days of last 15
	Flow(cfs)	Flow(cfs)) at 40+ cfs
Below River Intake			42 [e]	45	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1.7	2			
Mazourka Canyon Road			50	50	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			51	53	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station ¹			62	61	15
Pump Station			47	47	
Langemann Gate to Delta			3	3	
Weir to Delta			12	11	
LORP In Channel Average Flow ²			51	52	

Lower Owens River Project Flow Report for 01/21/2018

Pump Station Month-to-Date Average Flow 47 cfs

Blackrock Waterfowl Habitat Area

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date		
Thibaut	426 Acres	10/03/2017	2.1 cfs	10/16/2017		
Winterton	190 Acres	10/03/2017	1.2 cfs	10/16/2017		
Drew	0 Acres	05/17/2016	0 cfs	04/01/2015		
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011		
Total Flooded Area	616 Acres					
Off-River Lakes and Ponds						
Upper Twin Lake Gage Read		2.4 ft	(Last Colle	(Last Collected: 1/10/2018)		
Lower Twin Lake Gage Read		2.43 ft				
Goose Lake Gage R		2.74 ft				
Thibaut Pond Floode	d Area	28 Acres	S	(Last Collected: 10/03/2017)		

[e] LORP Intake Langemann gate has a mechanical problem, station is being current metered daily during repairs.

1. Above Pump Station not constructed, the flow is the sum of the Pump station discharge, the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

2. Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer:

http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm