Lower Owens River Project Flow Report for 01/31/2018

Augmenting Flows			Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily	,	# Days of
	Avg Flow(cfs)	Avg Flow(cfs)	Avg Flow(cfs)	Avg Flow(cfs	last 15) at 40+ cfs
Below River Intake	1 1011 (010)	11011(0.0)	42 [e]	44	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1	2			
Mazourka Canyon Road			44	50	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			53	52	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station ¹			59	61	15
Pump Station			47	47	
Langemann Gate to Delta			3	3	
Weir to Delta			9	11	
LORP In Channel Average Flow ²			50	52	

Pump Station Month-to-Date Average Flow 47 cfs

Blackrock Waterfowl Habitat Area

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date	
Thibaut	438 Acres	01/22/2018	2.1 cfs	10/16/2017	
Winterton	201 Acres	01/22/2018	1.2 cfs	10/16/2017	
Drew	0 Acres	05/17/2016	0 cfs	04/01/2015	
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011	
Total Flooded Area	639 Acres				
Off-River Lakes and	d Ponds				
Upper Twin Lake Gage Read 2		2.48 ft	(Last Collected: 01/24/2018)		
Lower Twin Lake Gage Read		2.58 ft			
Goose Lake Gage Read		2.54 ft			
Thibaut Pond Flooded Area 28		28 Acres	S	(Last Collected: 01/22/20	

[[]e] LORP Intake Langemann gate has a mechanical problem, station is being current metered daily during repairs.

^{1.} Above Pump Station not constructed, the flow is the sum of the Pump station discharge, the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

^{2.} Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm