Lower Owens River Project Flow Report for 03/21/2018

Augmenting Flow			Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily	•	# Days of
3	Avg Flow(cfs)	Avg Flow(cfs)	Avg Flow(cfs	Avg) Flow(cfs	last 15) at 40+ cfs
Below River Intake	(0.0)	()	44	43	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1.2	1			
Mazourka Canyon Road			51	51	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			56	58	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station ¹			60	60	15
Pump Station			47	46	
Langemann Gate to Delta			4	4	
Weir to Delta			9	10	
LORP In Channel Average Flow ²			53	53	

Pump Station Month-to-Date Average Flow 46 cfs

Blackrock Waterfowl Habitat Area

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date		
Thibaut	438 Acres	01/22/2018	2.1 cfs	10/16/2017		
Winterton	201 Acres	01/22/2018	1.2 cfs	10/16/2017		
Drew	0 Acres	05/17/2016	0 cfs	04/01/2015		
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011		
Total Flooded Area	639 Acres					
Off-River Lakes and Ponds						
Upper Twin Lake Gage Read		2.52 ft	(Last Colle	(Last Collected: 03/21/2018)		
Lower Twin Lake Gage Read		2.43 ft				
Goose Lake Gage Read		2.46 ft				
Thibaut Pond Floode	d Area	28 Acres	S	(Last Collected: 01/22/2018)		

^{1.} Above Pump Station not constructed, the flow is the sum of the Pump station discharge, the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

^{2.} Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm