	Augmenting Flows		Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily		# Days of
	Avg Flow(cfs)	Avg Flow(cfs)	Avg Flow(cfs	Avg) Flow(cfs	last 15) at 40+ cfs
Below River Intake			84	<u>84</u>	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1.4	1			
Mazourka Canyon Road			76	84	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			69	73	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station ¹			56	55	15
Pump Station			36	44	
Langemann Gate to Delta			20	10	
Weir to Delta			0	1	
LORP In Channel Average Flow ²			71	74	

Lower Owens River Project Flow Report for 07/19/2018

Pump Station Month-to-Date Average Flow 44 cfs

Blackrock Waterfowl Habitat Area

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date			
Thibaut	0 Acres	05/08/2018	0 cfs	04/04/2018			
Winterton	128 Acres	07/11/2018	4 cfs	04/16/2018			
Drew	253 Acres	07/11/2018	5.6 cfs	04/04/2018			
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011			
Total Flooded Area	381 Acres						
Off-River Lakes and Ponds							
Upper Twin Lake Gage Read 2		2.35 ft	(Last Colle	(Last Collected: 7/11/2018)			
Lower Twin Lake Gage Read		2.38 ft					
Goose Lake Gage Re	ead	2.43 ft					
Thibaut Pond Floode	d Area	0 Acres	3	(Last Collected: 05/08/2018)			

1. Above Pump Station not constructed, the flow is the sum of the Pump station discharge,

the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

2. Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm