## Lower Owens River Project Flow Report for 08/17/2018

Augmenting Flow			Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily	,	# Days of
<b></b>	Avg Flow(cfs)	Avg Flow(cfs)	Avg	Avg	last 15 ) at 40+ cfs
Below River Intake	1 1000(013)	1 10W(CIS)	76	76	15
			10	70	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1.1	1			
Mazourka Canyon Road			63	65	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			55	58	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station <sup>1</sup>			45	53	15
Pump Station			37	44	
Langemann Gate to Delta			8	8	
Weir to Delta			0	1	
LORP In Channel Average Flow <sup>2</sup>			60	63	

Pump Station Month-to-Date Average Flow 45 cfs

## **Blackrock Waterfowl Habitat Area**

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date
Thibaut	0 Acres	05/08/2018	0 cfs	04/04/2018
Winterton	128 Acres	07/11/2018	2.5 cfs	08/16/2018
Drew	253 Acres	07/11/2018	5 cfs	08/16/2018
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011
Total Flooded Area	381 Acres			
Off-River Lakes and	l Ponds			
Upper Twin Lake Gage Read 2		2.37 ft	(Last Collected: 8/8/2018)	
Lower Twin Lake Gage Read		2.38 ft		
Goose Lake Gage Read		2.35 ft		
Thibaut Pond Flooded Area		0 Acres	;	(Last Collected: 05/08/2018

<sup>1.</sup> Above Pump Station not constructed, the flow is the sum of the Pump station discharge, the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

<sup>2.</sup> Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm