	Augmenting Flows		Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily		# Days of
	Avg Flow(cfs)	Avg Flow(cfs)	Avg Flow(cfs	Avg ) Flow(cfs	last 15 ) at 40+ cfs
Below River Intake			46	49	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1.3	1			
Mazourka Canyon Road			42	44	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			46	46	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station <sup>1</sup>			46	45	15
Pump Station			42	41	
Langemann Gate to Delta			4	4	
Weir to Delta			0	0	
LORP In Channel Average Flow <sup>2</sup>			45	46	

## Lower Owens River Project Flow Report for 11/3/2018

Pump Station Month-to-Date Average Flow 42 cfs

## **Blackrock Waterfowl Habitat Area**

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date		
Thibaut	0 Acres	05/08/2018	0 cfs	04/04/2018		
Winterton	121 Acres	09/14/2018	0.8 cfs	10/16/2018		
Drew	269 Acres	09/14/2018	1.8 cfs	10/16/2018		
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011		
Total Flooded Area	390 Acres					
Off-River Lakes and Ponds						
Upper Twin Lake Gage Read		2.51 ft	(Last Colle	(Last Collected: 10/31/2018)		
Lower Twin Lake Gage Read		2.17 ft				
Goose Lake Gage Re	ead	2.52 ft				
Thibaut Pond Floode	d Area	0 Acres	6	(Last Collected: 05/08/2018)		

1. Above Pump Station not constructed, the flow is the sum of the Pump station discharge,

the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

2. Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm